

2020/2021 School Year Annual AHERA Update

During the 2018/2019 school year all district buildings were re- inspected as required according to The United States Environmental Protection Agency's 40 CFR 763 subpart E. The inspections were performed by a Licensed Building Inspector and Asbestos Management Planner through the Pennsylvania Department of Labor and Industry from Environmental and Safety Training, Inc.

AHERA reports are available for review as required by law at each building. The AHERA reports are located in the Main Office of each building.

All abatement work that has or may take place in the District is performed by Licensed and Accredited Contractors while air monitoring is done by an independent consulting firm.

Abatement work may occur out of necessity to eliminate any potential health and safety Hazard. Abatement only occurs out of necessity to perform maintenance work or for emergency purposes otherwise asbestos is to remain undisturbed and intact.

Abatement work has occurred at the following locations during the 2020/2021 school year they are as follows.

Ringgold Administration Building 400 Main Street New Eagle

No abatement has occurred

Ringgold Maintenance and Transportation 46 Ginger Hill Road Finleyville

No abatement has occurred

Ringgold High School 1 Ram Drive Monongahela

No abatement has occurred

Ringgold Middle School 6023 Route 88 Finleyville

No abatement has occurred

Ringgold Middle School 2 RAM Drive Monongahela

No known asbestos exist

Ringgold Elementary School North 3685 Finleyville-Elrama Road Finleyville

No abatement has occurred

At the Conclusion of the 2015/2016 Construction/Renovation project NO asbestos or assumed asbestos containing materials remain in the Ringgold Elementary School North building.

Ringgold Elementary School South

No abatement has occurred

At this time there is no further Abatement projects planned. However as the need for Abatement may occur this page will be updated periodically to notify of any changes.

